

Fig.1




Fig.2

Fig.3




Fig.4a

Room Control

light1

TV

E-key

light2

air cond.

light3

Fig.4b

<u>notice for circulation</u>	<u>correspondence</u>
<div><div>• general cleaning</div><div>• emergency drill schedule</div></div>	

Fig.4c

shopping

○ household appliance

○ liquor

○ furniture

○ multimedia

○ gift

banner advertisement

Fig.5a

<p style="text-align: center;"><u>Request Reception</u></p> <p><input type="radio"/> request for home facility</p> <p><input type="radio"/> request for household appliance</p> <p><input type="radio"/> request for reform</p> <p><input type="radio"/> other request and comment</p>
--

Fig.5b

<p style="text-align: center;"><u>Advice Return</u></p> <table border="1"><tr><td>Answer:</td></tr></table>	Answer:
Answer:	




Fig.6




Fig.7




Fig.8




Fig.9

30

Mr. X X X X's facility status list

33

facility	model No.	mon. date	replacement time	comment	link
refrigerator	X X X X	June, 1996	Dec, 2000	icehouse check is required	X X X repair shop
dryer	X X X X	June, 1994	Oct, 2000	fan exchange is recommended	X X shop
fluorescent (living)	X X X X	Oct, 1998	Nov, 2000	exchange earlier	X X shop
copier	X X X X	Aug, 1998	Sep, 2000	lease period comes to end	X X Lease

31

Other Information

33

Ten years will pass from the prior outer work.

Please consider reform.

32

X X Engineering (X X Electric Works Agency)

Fig.10

Fig.11

Recommend the goods to the following customer s.					
customer	goods	type	TEL	E-mail	
× × house	dryer body or fan fluorescent(×4)	× × ×	99-9999	× × × @ × × × ×	
× × × Co.Ltd	air con. filter(×10)	× × ×	99-9999	× × × @ × × × ×	
× × office	personal computer(×3)	× × ×	99-9999	× × × @ × × × ×	




Fig.12




Fig.13




Fig.14